



REVISIONS				
E.C. NO.	REV.	DESCRIPTION	BY	DATE
	A	DRAWING RELEASED	CE	1/04
0928	B	UPDATED DRAWING	SH	4/09

NOTES:

- RUN THE THREE CABLES FOR THE FWD THROTTLE QUADRANT UNDER THE HORIZONTAL FRAME TUBES AT STATIONS #4 & #5.
- RUN THE CABLES THRU STATION #2 & #3 BULKHEADS PRECEDING FWD TO THE PROPER MECHANICAL DEVICE EACH CABLE ATTACHES TO.
- MOUNT THE RADIATOR DOOR CONTROL LEVER ASSEMBLY (MC05-230) INSIDE THE COCKPIT ON THE LH SIDE OF THE PILOT, IN DESIRED LOCATION.
- WHEN MOUNTING (MC05-230) TO THE RADIATOR EXHAUST DOOR, BE SURE THE DOOR IS CLOSED & MC05-230 IS IN THE FWD POSITION. ATTACH CABLE TO MC05-230 & ROUTE CABLE TO RADIATOR DOOR AFT OF STATION #10. (AS SHOWN)

NOTE

- HORIZONTALLY, ONLY TWO ENGINE CABLES ARE REQUIRED IF A PROP. GOVERNOR IS NOT USED.


TITAN AIRCRAFT SUPPLY
 1419 STATE ROUTE 45 SOUTH
 AUSTINBURG, OHIO 44010

DRAWN C. EMERY		DATE 1/14/04	DETAIL NAME THROTTLE CABLES & RADIATOR DOOR CABLE INSTRUCTIONAL	
CHECKED R. INGLE		DATE 7/27/10	SCALE 1/16"=1"	PART NO.
APPROVED K. BROOKS		DATE 8/4/10	ASSEMBLY NAME FOR AIRCRAFT'S USING HYDRAULIC PROPS	
			PART NO.	DRAWING NO. C11
			DRAWING NO. B T51-04-INS-1001-B	

THIS DOCUMENT PROPRIETARY TO TITAN AIRCRAFT, AND IS NOT TO BE USED, CIRCULATED, REPRODUCED, COPIED, OR DISCLOSED IN ANY MANNER WITHOUT PRIOR WRITTEN PERMISSION OF AN AUTHORIZED OFFICIAL OF TITAN AIRCRAFT.